

# VISUAL INSPECTION SUMMARY REPORT

## Optronics S.A. de C.V. FiberChek2™


May 30, 2022, 7:44:54 PM  
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de  
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.  
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	<b>S100757-23221504A1</b>
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

\*\*PASS\*\*

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ <sup>2</sup> )	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	4	2.24225	PASS	0
<b>Epoxy Gap:</b>	PASS		<b>Fiber Type:</b>	Simplex		<b>Core Size:</b>	9



# VISUAL INSPECTION SUMMARY REPORT

## Optronics S.A. de C.V. FiberChek2™


May 30, 2022, 7:44:54 PM  
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de  
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.  
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	<b>S100757-23221504B1</b>
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

\*\*PASS\*\*

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ <sup>2</sup> )	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	4	2.24225	PASS	0
<b>Epoxy Gap:</b>	PASS		<b>Fiber Type:</b>	Simplex		<b>Core Size:</b>	9



# VISUAL INSPECTION SUMMARY REPORT

## Optronics S.A. de C.V. FiberChek2™


May 30, 2022, 7:44:54 PM  
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de  
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.  
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	<b>S100757-23221504B2</b>
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

**\*\*\*PASS\*\*\***

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ <sup>2</sup> )	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	4	2.24225	PASS	0
<b>Epoxy Gap:</b>	PASS		<b>Fiber Type:</b>	Simplex		<b>Core Size:</b>	9



# VISUAL INSPECTION SUMMARY REPORT

## Optronics S.A. de C.V. FiberChek2™

May 30, 2022, 7:44:54 PM  
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de  
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.  
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	<b>S100757-23221504A2</b>
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

**\*\*\*PASS\*\*\***

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ <sup>2</sup> )	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	4	2.24225	PASS	0
<b>Epoxy Gap:</b>	PASS		<b>Fiber Type:</b>	Simplex		<b>Core Size:</b>	9

